New Jersey Department of Environmental Protection Historic Preservation Office

PROPERTY REPORT

Property ID:

-2141053027

Property Name: Elizabeth Dye House Ownership: Private Address: 101 N Main ST **ZIP:** 08512 Apartment #:

PROPERTY LOCATION(S):

County: Municipality: **Local Place Name: USGS Quad:** Block: Lot: **MIDDLESEX** Cranbury township Cranbury 25

Hightstown

30.01

Property Photo:



Old HSI Number: NRIS Number: HABS/HAER Number:

Description:

The Elizabeth Dye House at 101 North Main Street is a two-and-a-half-story, two-bay, three-pile, frame Queen Anne style residence constructed in 1897 with a two-story rear addition. The house has a cube-shaped massing with a deeply hipped (nearly pyramidal) roof and protruding bays on each elevation. The roof is sheathed with slate shingles and features overhanging eaves clad with vinyl siding. Small returns are located in the three gables over the protruding bays, one of which is located on the south half of the main (east) elevation. A replacement half-circle attic window is located in each of these gables. The exterior of the entire dwelling is clad in vinyl siding. Fenestration consists of one-over-one vinyl-sash replacement windows, some of which are paired. The south half of the main elevation is a shallow protruding bay with a wide center panel containing a paired window on each floor and angled side panels with a window on each floor level. The front porch is a hipped roof element with an inset gable at its northern terminus over the entrance. The eaves of the porch are supported by unfluted lonic columns connected by a low railing. The entrance is a single wood replacement door with three lancet-shaped inset lights over a crossbuck. Brick steps with three sets of iron railings lead to the grade of the front lawn.

The south elevation faces onto Plainsboro Road. The cladding materials of the core are repeated: slate shingles on the roof and vinyl-clad walls. All windows are one-over-one windows that appear to be replacement units. The protruding bay is aligned with the west wall and occupies half of the wall surface. Like the front bay, it has a wider center panel with a paired window on the second floor but a single window on the first floor. The front porch wraps around this elevation, with a curved corner near the intersection. The north wall of the core

Survey Name: Cranbury CLG Survey 2017

✓ (Primary Contact)

Page 1

Surveyor: Kristen Herrick

Organization: RGA, Inc.

-2141053027

Property ID:

repeats the cladding of the main elevation. The protruding bay is aligned with the west wall of the core and features a gable over a rectangular bay. The windows of the protruding bay are a half-circle attic unit and paired one-over-one vinyl sash replacement units on the lower floors. The house has a stucco-clad foundation.

The rear addition is a two-story, one-bay extension that is aligned with the north wall of the core. Its gabled roof is clad with slate shingles and features a molded cornice with returns on the west end and a square brick interior slope chimney near the intersection with the core. The walls are clad with vinyl siding and feature replacement one-over-one windows installed irregularly over the wall surface. Weathering on the siding indicates that some windows formerly had flanking shutters. A small one-story addition on the south elevation of the rear addition has a hipped roof, frame walls clad with vinyl siding, a small one-over-one window on the south elevation, and a late nineteenth century door on the west elevation opening onto a brick stoop with an iron railing.

Character-defining elements of the dwelling include the semi-hexagonal projecting bays and return cornices in the gable ends.

History: The 1916 Sanborn Atlas depicts the house without its rear addition. At that time, the front porch wrapped around the north elevation as well, with an overall C-shaped. The Sanborn Atlas of 1933 does not cover this portion of Cranbury. The rear addition had been added prior to the historic aerial photograph of 1940, and the house has retained its overall shape since that time.

Settina:

The Elizabeth Dye House at 101 North Main Street is sited on a rectangular parcel (Block 25, Lot 30.01) located on the west side of North Main Street in Cranbury Township, Middlesex County, New Jersey. The parcel is bounded by North Main Street to the east and Plainsboro Road to the south. The dwelling is oriented with its primary elevation facing east and is set back approximately 15 feet from North Main Street. A concrete sidewalk spans the east and south sides of the parcel. A paved parking area adjoins the dwelling to the west, accessed by paved driveways on the east and south sides of the parcel. The property is lightly wooded. The Elizabeth Dye House at 101 North Main Street is located in a primarily residential neighborhood surrounded by other residential properties dating from the mid-nineteenth to the early twentieth centuries.

Registration and Status National Historic Landmark?:

National Register: 9/18/1980 SHPO Opinion:

Dates: New Jersey Register: 8/9/1979 Local Designation: 9/26/1988

Determination of Eligibility: 3/25/1977 Other Designation:
Certification of Eligibility: Other Designation Date:

☐ Eligibility Worksheet included in present survey? ☐ Is this Property an identifiable farm or former farm?

Location Map:

Plainsboro Rd Plainsboro Rd

40 80

Site Map:

Survey Name: Cranbury CLG Survey 2017

Cranbury CLG Survey 2017 0

Parcels (Block/Lot)

Surveyor: Kristen Herrick

Organization: RGA, Inc.

✓ (Primary Contact)

Property ID: -2141053027

Page 2

Author:	Title:				Year:	HPO Accession #:	(if applicable)
Walsh, Ruth	National Register of Historic Places Nomination for the Cranbury Historic District, Cranbury Township, Middlesex County, New Jersey			1979			
Heritage Studies	Preserving Historic Cranbury Village				1989		
Cranbury Historical and Preservation Society	Property File, 101 North Main Street						
Additional Information:							
The 1989 Heritage Studies Cranbury Historic District. Street as a contributing re More Research Needed	RGA concurs w source due to its	rith the previous evalua	ation and red	commends th	ne Elizab	eth Dye House at 101	North Main
WILLE KESEAICH NEEGEG	: Criec	keu-res)					
INTENSIVE-LEVEL USE		reu-Tes)					
	ONLY:	0 Building	0	Bridge			
INTENSIVE-LEVEL USE	ONLY:	0 Building 0 Structure	0	Landscape			
INTENSIVE-LEVEL USE	ONLY:	0 Building	_	Ū			
INTENSIVE-LEVEL USE Attachments Include	ONLY:	0 Building 0 Structure 0 Object	0	Landscape			
INTENSIVE-LEVEL USE Attachments Include Historic District ?	ONLY: d: Cranbury Histo	0 Building 0 Structure 0 Object	0	Landscape			

Survey Name: Cranbury CLG Survey 2017

7/25/2017

Surveyor: Kristen Herrick

Organization: RGA, Inc.

Date form completed:

Property ID: -2141053027

Page 3

✓ (Primary Contact)