New Jersey Department of Environmental Protection Historic Preservation Office

## PROPERTY REPORT

Property ID:

1504896299

Property Name:79 North Main StreetOwnership:PrivateAddress:79 N Main STApartment #:ZIP:08512

PROPERTY LOCATION(S):

 County:
 Municipality:
 Local Place Name:
 USGS Quad:
 Block:
 Lot:

 MIDDLESEX
 Cranbury township
 Cranbury
 23
 42.01

## **Property Photo:**



Old HSI Number: NRIS Number: HABS/HAER Number:

## **Description:**

79 North Main Street is a one-story, three-bay, one-pile, frame commercial building with a storefront obscuring its gabled roof. The front of the building is clad in wood clapboard siding and contains a commercial appearance with a recessed canted entrance between large multilight display windows. The central entrance consists of a single door with a large pane above a quatrefoil panel. A pent extends above the recessed entrance.

The north and south elevations of the building are identical. The gabled roof is clad with asphalt shingles, and the walls are solid wood clapboard with no windows. The building has a stone foundation.

Character-defining elements of the building include a parapet roof and a canted commercial entrance featuring wood windows with multiple inset lights.

History: The 1916 Sanborn map shows 79 North Main Street as a grocery. The 1933 Sanborn Atlas shows the building with the same appearance. 79 North Main Street once served as Harold O'Neil's Candy Store. A gas pump was located on the sidewalk in front of the building until 1979.

## Setting:

Survey Name: Cranbury CLG Survey 2017

Surveyor: Kristen Herrick

Organization: RGA, Inc.

Property ID:

✓ (Primary Contact)

1504896299

rty ID: Page 1

Township, Middlesex County, New Jersey. The building is oriented with its primary elevation facing southeast and is set back approximately ten feet from North Main Street. A concrete sidewalk spans the east side of the parcel. Trees are planted along the curb between the building and North Main Street. 79 North Main Street is located in a mixed residential and commercial neighborhood surrounded by commercial and residential properties dating from the mid-nineteenth to the early twentieth centuries. Registration National Historic Landmark?: and Status **National Register: SHPO Opinion:** Dates: **New Jersey Register: Local Designation: Determination of Eligibility:** Other Designation: Certification of Eligibility: Other Designation Date: ☐ Eligibility Worksheet included in present survey? ☐ Is this Property an identifiable farm or former farm? **Location Map:** Site Map: (Location Map Not Available) **BIBLIOGRAPHY: Additional Information:** The 1989 Heritage Studies survey identified 79 North Main Street as a contributing resource to the Cranbury Historic District. RGA concurs with the previous evaluation and recommends 79 North Main Street as a contributing resource due to its date of construction and design. More Research Needed? (checked=Yes) **INTENSIVE-LEVEL USE ONLY:** Attachments Included: 0 Building 0 Bridge Structure 0 Landscape 0 Object 0 Industry **Historic District? V** District Name: Cranbury Historic District Status: Contributing Survey Name: Cranbury CLG Survey 2017 **Property ID:** Page 2 1504896299 ✓ (Primary Contact)

Surveyor: Kristen Herrick

Organization: RGA, Inc.

79 North Main Street are sited on an L-shaped parcel (Block 23, Lot 42.01) located on the west side of North Main Street in Cranbury

	ological Site/Deposits? ntial sites. If Yes, please desc	cribe briefly)
Conversion Problem?  Date form completed:	ConversionNote:	Null

Survey Name: Cranbury CLG Survey 2017

Surveyor: Kristen Herrick

Organization: RGA, Inc.

✓ (Primary Contact)

1504896299

Property ID:

Page 3