New Jersey Department of Environmental Protection Historic Preservation Office

PROPERTY REPORT

PROPERTY REPORT Property ID:					454216687	
Property Name:	8 Maplewood Avenue			Owners	nip: Private	
Address:	8 MAPLEWOOD AVE		Apartment #:	2	ZIP: 08512	
PROPERTY LOCATION(S):						
County:	Municipality:	Local Place Name:	USGS Quad:	Block:	Lot:	

MIDDLESEX Cranbury township 33

28

Property Photo:



Old HSI Number:

NRIS Number:

HABS/HAER Number: 8

Description:

PS&S recommends that the residence at 8 Maplewood Avenue, constructed between 1850 and 1876, is a contributing property in the Cranbury Historic District. The garage on the property, built between 1947 and 1953, is non-contributing.

The 2-story, gable-roofed, L-plan, asbestos shingle-clad, main volume of this frame residence on a parged foundation is 4 bays wide and 3 bays deep. A 1-story, hip-roofed porch on turned posts extends across the northwest, main elevation of the northwestern portion of the main volume and wraps around the southwest side to shelter a secondary entrance into the rear, southeastern portion of the main volume. A 2-story, gable-roofed addition projects from the southeast corner of the residence. The roofs are clad in asphalt shingle with eave returns at the gable-ends, and the windows predominantly have historic 6/6 wood sash and historic 2/2 wood sash with applied shutters. An interior brick chimney projects from the gable ridge of the northern portion of the main volume. The front porch is accessed by a straight stair and includes historic wood posts, a simple rail, and square-section balusters. The residence is accessed by 2 historic doors, with 1 in the south bay of the north volume and 1 in the north bay of the south volume. A window is in each of the remaining bays on each floor. A casement window lights the first floor of the rear volume and a 1/1 window lights the second floor. A pent eave divides the 2 floors. The south, side elevation includes a window on each floor of the main volume, a small, sliding window on the first floor of the rear volume, and a 1/1 window on the second floor. The east, rear elevation is not visible from the public right-of-way. The north, side elevation has a window in each bay of each floor except the central bay of the first floor.

Survey Name:	Cranbury Local Historic District Survey 2018		Property ID:	Page 1
Principal Investigator:	Emily Cooperman	(Primary Contact)	454216687	
Organization:	Paulus, Sokolowski & Sartor			

The 1 $\frac{1}{2}$ -story, cross gable-roofed garage located to the northeast of the residence includes 2 entrances and 2 car ports, with a shuttered opening on the second floor.

Historic maps show that the residence at 8 Maplewood Avenue was built between 1850 and 1876. Current homeowners report the house to have been built circa 1858. It is identified as the property of "P. R. Bergen" on the 1876 Everts & Stewart map, and inventoried in the 1980 National Register Nomination for the Cranbury Historic District as dating to the mid-19th century. A view of the house seen from Maplewood Avenue (Brennan and Brennan 1995: 66) shows the same organization of the main volume, with 6/6 windows in the northern section and 2/2 windows in the southern, and clapboard cladding. Louvered shutters are visible on most of the windows. The front porch appears to be as it is today, but without a railing and the larger bottom plinths of the posts. The residence was identified as the "Stahl Homestead." The building was detailed in the 1916 Sanborn map as a 2-story. L-plan. cross gable-roofed, frame dwelling with a 1-story. slate or metal-roofed, partial wrap-around front porch and a small, 1-story, composite-roofed secondary building immediately behind the residence. The 1933 Sanborn shows no alterations. The smaller secondary building was removed after 1933 and the current. Historic aerial photographs indicate that the current, larger garage was built to the northeast of the residence between 1947 and 1953. The 1974 photographic inventory of Cranbury historic buildings in the collection of the Cranbury Historical and Preservation Society shows the building's northeast and northwestern elevations, and indicates that the current porch railing and asbestos shingle were present at this date. The 1980 National Register Nomination for the Cranbury Historic District Historic inventory noted the shingle and the combination of 6/6 and 2/2 sash. The 1989 Heritage Studies inventory noted that the rear portion of the main volume may have been a historic addition, which is supported by both visual evidence and comparison to neighboring properties on Maplewood Avenue aerial photographs. Historic aerial photographs indicate that the garage was expanded into its present, cross gable-roofed configuration between 1979 and 1987. A 2story, gable-roofed rear addition was constructed on the southeast corner of the residence between 1987 and 2002.

This property is a contributing property in the historic district because it retains integrity and such character-defining historic features as the massing of its historic main volume, its historic front porch, historic chimneys, and historic window sash and wood doors.

Setting:

Maplewood Avenue is an approximately half-mile long primarily residential street that connects N. Main Street, to the northwest, to Route 130, to the northeast. Maplewood runs parallel to N. Main Street between Scott Ave. and Park Place, after which it turns to the northeast to form a southwest extension of Cranbury-South River Road.

Registration and Status Dates:	National Historic Landmark?:			
	National Register:	9/18/1980	8/1980 SHPO Opinion:	
	New Jersey Register:	8/9/1979	Local Designation:	9/26/1988
	Determination of Eligibility:	3/25/1977	Other Designation:	
	Certification of Eligibility:		Other Designation Date:	
🗌 Eligibility Wo	orksheet included in present survey	? 🗌 Is this F	Property an identifiable farm	or former farm?

Survey Name:	Cranbury Local Historic District Survey 2018		Property ID:	Page 2
Principal Investigator:	Emily Cooperman	(Primary Contact)	454216687	
Organization:	Paulus, Sokolowski & Sartor			

Location Map:

Site Map:





BIBLIOGRAPHY:


Author:	Title:	Year:	HPO Accession #:	(if applicable)
Heritage Studies	Preserving Cranbury Township	1989		
(None Listed)	Aerial and street view photography for 1931, 1940, 1947, 1953, 1957, 1963, 1969, 1970, 1972, 1979, 1987, 1995, 2002, 2006, 2007, 2008, 2010, 2012, 2013, and 2015 available at historicaerials.com and for 1995, 2002, 2006, 2007, 2008, 2010, 2013, 2016, and 2017 available through Google Earth			
(None Listed)	1850 Otley and Keily Map	1850		
(None Listed)	1933 Sanborn Map	1933		
Brennan, Peggy and Frank J. Jr.	Images of America: Cranbury, Volume II	1998		
Brennan, Peggy and Frank J. Jr.	Images of America: Cranbury	1995		
Chambers, John Whiteclay II	Cranbury: A New Jersey Town from the Colonial Era to the Present	2012		
(None Listed)	1876 Everts and Stewart Map	1876		
(None Listed)	1916 Sanborn Map	1916		
Walsh, Ruth	National Register of Historic Places Nomination for the Cranbury Historic District, Cranbury Township, Middlesex County, New Jersey	1979		

Additional Information:

1202_33_28 / 2STY - SFD / 1880

More Research Needed?

(checked=Yes)



Page 3

INTENSIVE-LEVEL USE C	NLY:					
Attachments Included:		Building	0	Bridge		
	0	Structure	0	Landscape		
	0	Object	0	Industry		
Historic District ?	\checkmark					
District Name:	Cranbury Historic	District				
Status:	Contributing					
Associated Archeological Site/Deposits?						
Conversion Problem?	Conversior	Note:				

Date form completed:

8/17/2018

Survey Name:	Cranbury Local Historic District Survey 2018		Property ID:
Principal Investigator:	Emily Cooperman	(Primary Contact)	454216687
Organization:	Paulus, Sokolowski & Sartor		

Page 4