New Jersey Department of Environmental Protection Historic Preservation Office

PROPERTY REPORT

Property ID:

-967757615

Ownership: Private **Property Name:** 33 South Main Street Address: 33 S MAIN ST **ZIP:** 08512 Apartment #:

PROPERTY LOCATION(S):

County: Municipality: **Local Place Name: USGS Quad:** Block: Lot:

MIDDLESEX Cranbury township 35 11

Property Photo:



Old HSI Number: NRIS Number: HABS/HAER Number: 78

Description:

PS&S recommends that 33 S. Main Street, which includes a historic residence built circa 1800 and historic garage built circa 1920, is a contributing property in the Cranbury Historic District.

The 2-story, gable-roofed, rectangular-plan main block of this painted wood shingle-clad, frame dwelling on a stone and parged foundation is 5 bays wide and 2 bays deep and is backed on the southeast by a 2-story, gable-roofed, partial-width secondary volume. The rear volume is in turn flanked by a 1-story, shed-roofed, enclosed porch volume on the southwest elevation. Gable-roofed, segmental arch doorhoods on scroll brackets in located on both the northwest, main and northeast, side elevation. The roofs are predominantly clad in asphalt shingle and the windows predominantly have 6/1 replacement wood sash. An exterior brick chimney projects from the center of the northeast elevation of the main volume. The primary entrance to the residence, located in the central bay of the northwest elevation, is accessed by a straight brick stair with wrought iron rail and includes a historic 8-light door with extended recessed panels and a historic, fluted pilaster door surround that joins the door hood. The remaining bays are regularly fenestrated on both floors. The southwest, side elevation is lighted in the main block by a triple window on the first floor and a double window on the second floor. The enclosed rear porch is lighted by 2 fixed, 8-light windows and includes a secondary door in the northwest bay. The second floor of the rear volume is lighted by 2 single windows. The northeast, side elevation includes an 18-light door in the southeast bay with a door surround that matches that of the primary entrance, though the brackets of the door hood are shaped with a simpler profile. A single window lights the northwest bay of

Survey Name: Cranbury Local Historic District Survey 2018

Property ID:

-967757615

Page 1

Emily Cooperman Principal

Investigator:

(Primary Contact)

Organization: Paulus, Sokolowski & Sartor

the main block. The rear volume is lighted by 2 single windows on the first floor and a smaller, double, 1/1 window on the second floor. The southeast, side elevation is not visible from the public right-of-way. The 1-story, gable-roofed, frame garage located to the southeast of the residence, is accessed by a garage door on the northeast elevation and is lighted by a historic window on the northwest elevation.

Historic maps indicate that South Main Street includes some of the earliest development in Cranbury. The settlement began in 1736 with the construction of a mill on the south banks of the Cranbury Brook and, by 1810, developed into a small village. The 1980 National Register of Historic Places Nomination for the Cranbury Historic District indicates that the residence at 33 S. Main Street was constructed circa 1920. Historic maps and visual evidence, however, indicate an earlier construction date. Current homeowners suggest that the stone foundation and hand-hewn interior beams of the southwest bays of the main block point to a late 18th-century construction campaign. Historic maps indicate that a residence was built on the property for "Mrs. Vanhorn" by 1876. This residence is documented in the 1916 Sanborn Map as a 2-story, rectangular-plan, frame dwelling fronted by a 1-story, partial-width front porch and backed by a 2-story, partialwith rear volume which is in turn flanked to the southeast by a 1-story porch. A 1-story outbuilding located to the southeast of the residence and 2-story outbuilding located in the northeast corner of the lot are also documented on the property. Visual evidence, such as changes in the foundation material, suggest that this residence expanded the earlier, 18th-century dwelling. The 1933 Sanborn Map records a dwelling with the same massing, but the 1-story outbuilding has been demolished and the 2-story outbuilding has been replaced by a 1-story garage in the southeast corner of the lot. Historic aerial photographs indicate that the rear volume was expanded to its current size between 1933 and 1940. Visual evidence suggests that during the renovation campaign the front porch was removed and replaced by a gabled door hood, a matching door hood to a secondary side entrance was added, paneled shutters were added to the windows, and the chimney was expanded. Imagery from the 974 photographic inventory documents the residence's current 8-light front door and 6/1 window sash, though visual evidence suggests that the window sash has been replaced within the last ten years. The rear porch was enclosed at an indeterminate time.

33 S. Main Street is a contributing property in the Cranbury Historic District because it retains integrity and historic, character-defining features such as the historic massing of the main volume, the historic shingle siding, and the historic front door. The garage retains historic clapboard siding and historic windows.

Setting:

South Main Street stretches from Brainerd Lake to the southern edge of Cranbury and is characterized by freestanding single-family residences of moderate scale ranging in date from the early 19th century to the early 20th century.

Registration and Status Dates:	National Historic Landmark?:				
	National Register: 9/18/1980		SHPO Opinion:		
	New Jersey Register:	8/9/1979	Local Designation: 9/26/1988		
	Determination of Eligibility:	3/25/1977	Other Designation:		
	Certification of Eligibility:		Other Designation Date:		
☐ Eligibility Wo	orksheet included in present survey	? Is this	Property an identifiable farm	or former farm?	


Survey Name: Cranbury Local Historic District Survey 2018 Property ID: Page 2

Principal Emily Cooperman (Primary Contact) -967757615

Organization: Paulus, Sokolowski & Sartor

Investigator:

Location Map:



Site Map:



BIBLIOGRAPHY:

Author:	Title:	Year:	HPO Accession #:	(if applicable)
(None Listed)	Aerial and street view photography for 1931, 1940, 1947, 1953, 1957, 1963, 1969, 1970, 1972, 1979, 1987, 1995, 2002, 2006, 2007, 2008, 2010, 2012, 2013, and 2015 available at historicaerials.com and for 1995, 2002, 2006, 2007, 2008, 2010, 2013, 2016, and 2017 available through Google Earth			
Chambers, John Whiteclay II	Cranbury: A New Jersey Town from the Colonial Era to the Present	2012		
(None Listed)	1916 Sanborn Map	1916		
Heritage Studies	Preserving Cranbury Township	1989		
(None Listed)	1933 Sanborn Map	1933		
(None Listed)	1876 Everts and Stewart Map	1876		
Brennan, Peggy and Frank J. Jr.	Images of America: Cranbury, Volume II	1998		
Walsh, Ruth	National Register of Historic Places Nomination for the Cranbury Historic District, Cranbury Township, Middlesex County, New Jersey	1979		
Brennan, Peggy and Frank J. Jr.	Images of America: Cranbury	1995		
(None Listed)	1850 Otley and Keily Map	1850		
Additional Information: 1202_35_11 (TO REFUR	BISH) / 2STY - SFD / 1840			

Survey Name: Cranbury Local Historic District Survey 2018

(checked=Yes)

Principal Emily Cooperman

Investigator:

More Research Needed?

Organization: Paulus, Sokolowski & Sartor

Property ID: -967757615

(Primary Contact)

Page 3

INTENSIVE-LEVEL USE O	NLY:						
Attachments Included		Building	0 Bridge				
			0 Landscape				
		Object	0 Industry				
Historic District ?	✓						
District Name:	Cranbury Historic District						
Status:	Contributing						
Associated Archeolo (known or potentia		its? ase describe briefly)					
Conversion Problem?	Conversion	nNote:					
Date form completed:	8/24/2018						

Survey Name: Cranbury Local Historic District Survey 2018

(Primary Contact)

Property ID: -967757615

Principal Emily Cooperman **Investigator:**

Organization: Paulus, Sokolowski & Sartor

Page 4